ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M118207

 Date Received:
 12/20/07

 Date Extracted:
 12/27/07

 Date Analyzed:
 12/27/07

 Matrix:
 Water

 Units:
 ug/L (ppb)

Client:
Project:
Lab ID:
Data File:
Instrument:

Alaskan Copper Works PO M118207, F&BI 712226

712226-01 x10 712226-01 x10.017 ICPMS1

Operator: Hr

Internal Standard: Germanium

% Recovery: 105

Lower Limit: 60

Upper Limit: 125

Concentration
Analyte: ug/L (ppb)

Chromium 589
Nickel 640
Copper 384
Zinc 23.5

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client:
Date Received: Not Applicable Project:
Date Extracted: 12/27/07 Lab ID:
Date Analyzed: 12/27/07 Data File
Matrix: Water Instrume
Units: ug/L (ppb) Operator

Project: PO M118207, F&BI 712226 Lab ID: I7-490 mb Data File: I7-490 mb.008 Instrument: ICPMS1 Operator: Hr

Alaskan Copper Works

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 85 60 125

 $\begin{array}{c} & & & Concentration \\ Analyte: & ug/L \ (ppb) \end{array}$ Chromium $\begin{array}{c} <5 \\ Nickel \\ Copper \\ Cinc \end{array}$ <1

ENVIRONMENTAL CHEMISTS

Date of Report: 01/02/08 Date Received: 12/20/07

Project: Metro Self Monitor, PO M118207, F&BI 712226

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 712237-12 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	13.1	12.5	5	0-20
Nickel	ug/L (ppb)	15.4	15.6	1	0-20
Copper	ug/L (ppb)	1.79	1.61	11	0-20
Zinc	ug/L (ppb)	3.46	3.21	7	0-20

Laboratory Code: 712237-12 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria	
Chromium	ug/L (ppb)	20	13.1	105 b	50-150	
Nickel	ug/L (ppb)	20	15.4	100 b	50-150	
Copper	ug/L (ppb)	20	1.79	93	50-150	
Zinc	ug/L (ppb)	50	3.46	98	50-150	

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	93	70-130
Nickel	ug/L (ppb)	20	102	70-130
Copper	ug/L (ppb)	20	105	70-130
Zinc	ug/L (ppb)	50	95	70-130

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

712226	*	* 8 * *	SAN	IPLE	СНАІ	N OF C	JSI	OI	Y	ļ	YΕ	4	2.	-21). ()	F		AIG	<u>_</u>		
7	1.0		٧ اخر	SAMPI	EDS	ignature)					J.						ge#_	DOLINIE	of_		
Send Report To GRECO THOMPS				PROJE	CT NA	ME/NO.				Ť		PO	#	-	TURNAROUND TIME Standard (2)Weeks)						
Company ALASKAN Roppen Works			me	Ino	Self n	hon	For	2	1	n/I	187	(O)	2	Rush charges authorized by:							
Address 628 S.		ST											SAMPLE DISPOSAL								
City, State, ZIP SepTRE Up 98134					RKS										☐ Dispose after 30 days						
Phone #206-571-6037	Fax # 206	6-382-4	301						·						Return samples Will call with instructions						
										A	NAI	YSI	ES R	EQU	ESTI	ED					
Sample ID	Lab ID	Date	Time	Samp	le Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	のるのから	か 3					Not	es	
11876	-	p/ /	, .	1	- 3	,		_		+		+	쉬				_				
m 118207	δι	12/0/2	1:00	173	20	/	_	.,.		+	_	4									
	ļ		·																		
		,																			
					*										•						
				+-			-	-		-	\dashv	\dashv					\vdash				
	 						<u> </u>			-	_	\dashv				_	├	ļ			
																<u>L.</u>					
	Ź						Π												<u>.</u>		
			 			 	t	\vdash	$\vdash \vdash$		•			\vdash	-	\vdash	1	+		····	
Friedman & Bruya, Inc.		SIGNATU	TRIF.			PRINT	אוא יו	ME	<u></u>	اـــــ	Ч		CC	MP	ANV	<u> </u>	┸┰	DATE	\top	TIME	
3012 16th Avenue West	Relinquished	y:		PRINT NAME OTENSED Tayson					\top	COMP						12/0/07	T	1:30pm			
Seattle, WA 98119-2029	July 1				JIER L	Par	1	110	\ \	<u> </u>	+	FBI 12				200	計	:300			
Ph. (206) 285-8282					RAS TI REVIEWS					10.	<u> </u>			\dashv'	JAR	+	·				
Fax (206) 283-5044	Received by:									- :	\dashv						\dashv		十		
FORMS\COC\COC.DOC	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·		<u>. </u>												L				
, and the second								*	•		1	Sar	nple	es re	ceiv	ed:	a <u>ta</u>	<u>/6 °</u> c		×	

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 2, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 20, 2007 from the Metro Self Monitor, PO M118207, F&BI 712226 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0102R.DOC